


FIELD INSPECTION REPORT

Date of Inspection :	16.12.2020	District:	DAR BHANGA
Division :	DAR BHANGA-1	Length (km):	8.90 km
Name of the Road:	SURHACHATTI TO HATHAURI		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 3
b)	Condition of Surfacing Except two patches patches	S/U 5
c)	Riding Quality - d.o. -	S/U 5
d)	Road Camber	S/U 3
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No 75
f)	Contraction Joints provided or not (CC Pavement)	Yes/No 75
g)	Compaction of flank/slope & raincuts if any	Yes/No 75
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 8
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U 8
c)	Condition of railings/slab/approach for Bridges	S/SRI/U 40
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No 75
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: K. R. RANJAN

DESIGNATION: EE