FIELD INSPECTION REPORT

ivision	: Siwa	uー2 Length	(km): 4.85	Km-
		Tathaur Tol +	o talikh	urda.
	Programme:	MAINTENANCE		
Package No.: Road Id No.:				
	the Project:	Ongoing/Completed/Under M		
i de la compansión	a case of:	New Connectivity/Up gradation		
l. No.		Parameters to be checke	ed .	Remarks
1,	Payement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No —
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
3	Cross Drainage			
4: n:	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
a)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRIÆJ
<u>b)</u>	Condition of railings/slab/approach for Bridges		S/SRI/U	
c)	Road Furniture			in the second
.3. a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
		The state of the s	是各大的基础图	
4,	Compliance History Status of ATR's & any others			
a)	Status of A 1 1 3 2			

Unsatisfactory (U)

akesh Ranjan tanly. Executive Conginar ON.

(Signature)

NAME:

DESIGNATION: