

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020		District: Siwan.
Division : Siwan-2		Length (km): 7.85 Km.
Name of the Road: Tilmapur Siwan via Bisanpura.		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance /
Work is a case of:		New Connectivity/Up gradation/ Maintenance /

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U /
b)	Condition of Surfacing	S/U /
c)	Riding Quality	S/U /
d)	Road Camber	S/U /
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No /
f)	Contraction Joints provided or not (CC Pavement)	Yes/No /
g)	Compaction of flank/slope & raincuts if any	Yes/No Rain cut
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U /
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U /
c)	Condition of railings/slab/approach for Bridges	S/SRI/U /
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No /
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME:

DESIGNATION:

Rakesh Ranjan Pandey.
Executive Engineer.
% CG-1.