

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020	District: East Champaran	
Division : Motihari	Length (km): 6.00	
Name of the Road: Karaniga chiron Machine to Pachbhira Rd		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.: 31708208098	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance	old 3054	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓
a)	Road Junction condition	S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U M A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	→
Unsatisfactory (U)	

Bindu Rajak
(Signature) 17/12/20

NAME: Bindu Rajak

DESIGNATION: Executive Engineer
R.W.D.

Regional Laboratory Darbhanga