

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020 District : West Champaran.
 Division : R.W.D. North Beghal Length (km): 4.10 KM
 Name of the Road : - Betthi Ramdegar Road to Sikta na Dhubani
 Scheme/Programme: MAINTENANCE Ramouli
 Package No.: 24 Road Id No.: 3180900818
 Status of the Project: Ongoing Completed Under Maintenance - M/R-3054
 Work is a case of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition - TO be repair	S/U
b)	Condition of Surfacing - S	S/U
c)	Riding Quality - S	S/U
d)	Road Camber - S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes	Yes/No
f)	Contraction Joints provided or not (CC Pavement) yes	Yes/No
g)	Compaction of flank/slope & raincuts if any Reinment NO	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting S	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained yes	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others - HD	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

NAME:

Ratnesh Paswan.

DESIGNATION:

Executive Engineer

(Signature)

24/11/17.12.2020