

# FIELD INSPECTION REPORT


Date of Inspection : 17.12.2020	District: DARBHANGA
Division : DARBHANGA-2	Length (km): 4.5 Km
Name of the Road: NH 105 BANWAR TO KAUAHLE VIA NAYA SOON	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NO
g)	Compaction of flank/slope & raincuts if any	Yes/No YES
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRC
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U SRC
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	on NO Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Contractor is no more (died), FLOOD affected, reported in FDR

  
(Signature)

NAME: K.R. RANJAN

DESIGNATION: EB