

18

New MIR 3054

FIELD INSPECTION REPORT

Date Of Inspection		17/12/2020	District	Chojpur
Division		PWD	Length (km):	0.150
Name of the Road:		Kumhari road To 3 to Dhangana		
Scheme/Programme		MAINTENANCE		
Package No.:		Road Id No.: 10401802004		
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is a case of :		New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked		Remarks	
1	Pavement			
a)	Road Junction condition		✓ S/U	
b)	Condition of Surfacing		✓ S/U	
c)	Riding Quality		✓ S/U	
d)	Road Camber		✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No	
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No	
4	Compliance History			
a)	Status of ATR's & any others		NIL	

Overall Rating :

Satisfactory (S)

(S)


Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Name:

N.A. ISHRAT

(Signature)


 17/12/20
 EE

Designation

EE