

Date	Of Inspection	FIELD INSPEC	CTION REPORT		
Divi	sion Prop	171019	District Bhoppur		
Name of the Pood		Length (km):	1.50		
Scheme/Program		Tol to Davidia	Market Land		
Pack	Package No.:				
	is of the Project :		Road Id No.: 1040 18	02028	
Work is a second Comple		eteted/Under Maintenance			
SI No		New Connectivit	ty/Up gradation/Maintenance		
1		Parameters to be c	hecked	Remarks	
3)	Payment			Kemarks	
	Road Junction condition				
)	Condition of Surfacing				
)	Riding Quality			√S/U	
)	Road Camber		VS/U		
)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No 7		
)	Contraction Joints provided or not (CC Pavement)		Yes/No		
)	Compaction of flank/slope & raincuts if any		Yès/No		
	Cross Drainage			163/110	
	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N.		
	Condition of railings/slab/approach for Bridges			S/SRI/U	
	Road Furniture				
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
	Compliance History				
	Status of ATR's & any others		MIP		

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U) (Signature) 17 12/20

Name: N.A.ISHRAT

Desigination