

FIELD INSPECTION REPORT

Date of Inspection :	17-12-2020	District:	Aurangabad
Division :	Aurangabad	Length (km):	4.500
Name of the Road:	Keshar Road Nargash via Chata Debra		
Scheme/Programme:	MAINTENANCE (New Road Maintenance Policy 2018)		
Package No.:	MR-N/19-20	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No raincuts
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/UNY
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

NAME: RAM KUMAR MISHRA

(Signature)
 17/12/20
 E.E
 R. Lab
 Gulzarbag
 Patna