FIELD INSPECTION REPORT

Date of Inspection: 16.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (km) : 1.62	
Name o	f Road: P.M.G.S.Y Road to Jamin via Nayatola		
Scheme	Programme: NEW MAINTENANCE POLICY-20	18	
Package No. : 02		Road Id No.: 20703201019	
Status	of the Project : Ongoing		
Work i	s a case of : Maintenance		
	Permit		
a)	Road Junction condition		S
b)	Condition of Surfacing		S
c)	Riding Quality		S
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		ÑΑ
f)	Contraction Joints provided or not (CC Pavement)		NA
g)	Compaction of flank/slope & raincuts if any No		No.
	Constitution Const		
a)	Condition of head walls in Hume pipe culverts including its painting		NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N.		NA
c)	Condition of railings/slab/approach for Bridges		NA
	Should Exercise	and the second second	
a)	Whether sign board/informatory/cautionary Board Road marking are provided and Maintained	/km & 200m stones/Pavement	Yes
	Complete address		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	
SH (Signatu	(hr. 16.12 2000

NAME: KUMAR RAKESH

DESIGNATION: EXECUTIVE ENGINEER