FIELD INSPECTION REPORT

Date of Inspection: 16.12.2020			District : Bhagalpur	District : Bhagalpur	
Division: Bhagalpur Length (km): 2.119			Length (km): 2.119		
Name o	f Road : Gauradi	h Nadiyama Road			
Scheme	/Programme : OI	D MAINTENANCE P	OLICY-2013		
Package	ackage No.: Road Id No.: 20703208214				
Status o	of the Project : Or	ngoing			
Work is	a case of : Up gr	adation			
a)	Road Junction co	ondition		NA	
b)	Condition of Sur	facing		NA	
c)	Riding Quality			NA	
d)	Road Camber			NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			NA	
f)	Contraction Join	ts provided or not (CC)	Pavement)	NA	
g)	Compaction of f	lank/slope & raincuts if	any	NA	
		Constitution of the second			
a)	Condition of head walls in Hume pipe culverts including its painting			NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			NA	
(c)	Condition of railings/slab/approach for Bridges			NA	
a)	Whether sign b Road marking a	oard/informatory/cautic re provided and Mainta	onary Board/km & 200m stones/Pavement ined	NΛ	
7				,	
a)	Status of ATR's	& any others: Transfe	er to RCD		
L				·	
Over	all Rating :	Satisfactory (S)		NA	

Ovolan ranna

Satisfactory (S)		NA	
Satisfactory but requires Improve	ment (SRI)	NA	
Unsatisfactory (U)		NA	
ESH	(Signature) 6.12.72.72		

NAME: KUMAR RAKESH

DESIGNATION: EXECUTIVE ENGINEER