

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 5.4
Name of Road : Mirzanhat-Nadiama PMGSY (Mohanpur) - Hazudih		
Scheme/Programme : NEW MAINTENANCE POLICY-2018		
Package No. : 13		Road Id No.: NEA22000441
Status of the Project : Ongoing		
Work is a case of : Maintenance		
1	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)


Satisfactory but requires Improvement (SRI)

SRI

Unsatisfactory (U)

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER


(Signature) 16.12.2020