

FIELD INSPECTION REPORT


Date of Inspection : 16.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 1.5
Name of Road : L053-Nadiyama Road to PWD Jayhut (VR53)		
Scheme/Programme : NEW MAINTENANCE POLICY-2018		
Package No. :		Road Id No.: NEA22000443
Status of the Project : Ongoing		
Work is a case of : Maintenance		
Sr. No.	Parameters to be checked	Remarks
1 Pavement		
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	No
g)	Compaction of flank/slope & raincuts if any	No.
2 Canal Bridges		
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3 Road Furniture		
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes
4 Compliance History		
a)	Status of ATR's & any others : Work going on	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER


 (Signature) 16.12.2020