

FIELD INSPECTION REPORT

Date of Inspection : 16/12/20		District: Rohtash	
Division : Sasaram - 2		Length (km): 1.30 km	
Name of the Road: From Salempur chiksi road to manghessa			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 10301001030	
Status of the Project: <input checked="" type="checkbox"/> Ongoing/ <input type="checkbox"/> Completed/ <input type="checkbox"/> Under Maintenance			
Work is a case of: <input type="checkbox"/> New Connectivity/ <input checked="" type="checkbox"/> Up gradation/ <input type="checkbox"/> Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started

[Signature]
16-12-20
(Signature)

NAME: Er. Arun Kumar Mahato.