## FIELD INSPECTION REPORT

Date of Inspection : 1	8 12 20	District: Rohdosh	
Division: Bikramganj		Length (km): 6.90 KM	
Name of the Road: Dt	orgadin hospital	path to Naktque	
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.: 10301300819	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
	New Connectivity/Up gradation/ Maintenance/		

SI. No.	Parameters to be checked	Remarks
1.	Pavement	The state of the s
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (\$RI)	V
Unsatisfactory (U)	

Maintenance work in progress.

(Signature) 12.2020

NAME: Er. Arun Kumar Mahto