

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Patna</u>
Division : <u>Bach</u>	Length (km): <u>0.975 km</u>
Name of the Road: <u>PMGSY Road to Dasevashpur (Dharmpur)</u>	
Scheme Programme: <u>MAINTENANCE</u>	
Package No.:	Road Id No.:
Status of the Project:	☒ Ongoing ☐ Completed ☒ Under Maintenance
Work is a case of:	☒ New Connectivity ☐ Up gradation ☒ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S.I. ✓
b)	Condition of Surfacing	S.I. ✓
c)	Riding Quality	S.I. ✓
d)	Road Camber	S.I. ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & runouts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S.S.P. } N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S.S.P. }
c)	Condition of railings/slab approach for Bridges	S.S.P. }
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

" U "

[Signature]
14-12-2020
(Signature)

NAME: DHANANJAY KUMAR NIRALA
A.E