

MMGSY FIELD INSPECTION REPORT

Date of Inspection : 14.12.2020 District: Patna
Division : Buxh Length (km): 1.915 KM
Name of the Road: NH 30A Tamaria, Pul to Kerauli PMGSY Rd. to Bhojpu
Scheme/Programme: MAINTENANCE
Package No.: Road Id No.: ✓

Status of the Project: Ongoing/Completed/Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

" U "

(Signature) 14.12.2020

NAME: DHANANJAY KUMAR NIRALA
A-E