FIELD INSPECTION REPORT

te of I	Inspection: 6	2 20		nka
ision	2000	-2 A	The state of the s	298 KM.
		INTENANCE	Turdin (pm	1984)
			Road Id Non 2070 3	160 2120
	No.: P2R03F the Project: Ong	oing/Complete	d/Under Maintenance	
			Up gradation/ Maintenance	
l. No.	Parameters to be checked		Remarks	
1.	Pavement			
	Road Junction condition			· S/U
a)				S/U
b)	Condition of Surfacing			S/UV
c)	Riding Quality			S/UL
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No C
g)	Compaction of flank/slope & raincuts if any			Yes/No U
2.	Cress Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			nting S/SRI/L
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			· S/SRI/U
c)	Condition of railings/slab/approach for Bridges S			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			200m Yes/NoV
4.	Compliance Histo	ry		4 T 1 T 1 T 1 T 1 T 1 T 1 T 1 T 1 T 1 T
a)	Status of ATR's &	any others	Control	

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: Sampati Kr yadav.
DESIGNATION: AE