

FIELD INSPECTION REPORT

Dhoojga

(5)

Date of Inspection : 15/12/2020		District : Bongaiga
Division : Bongaiga-2		Length (km): 1.251 KM
Name of the Road: Ahirao Durga Ashan to Mardol hola		4.5Y (4.6M)
Scheme/Programme: MAINTENANCE		4TH Year
Package No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance	Road Id No.: 20703612016
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

N/A

Overall Rating :

Satisfactory (S)	S R I
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Sayan Kumar
DESIGNATION: JR

(Signature) 15/12/20