## FIELD INSPECTION REPORT



Date of	Inspection	T. ABIORI		
Divisio	Inspection: 15   10	70174		7
Name o	f the Road: Parker 2	Length (km): 0.422	KM	-
Name of the Road: Beldiaha Chowk to Beldiaha Scheme/Programme: MAINTENANCE, 4 Th Year			me Tala-	M,M.
Packag	No.:	4 In Year		(4,
Status o	f the Project: Ongoi	Road Id No.: 207036	2019	
(1) -1 :		Connectivity/Up gradation/ Maintenance		
SL No.	A CONTROL OF THE PARTY OF THE P	arameters to be checked	Remarks	
1.	Pavement	A CONTRACT OF THE PARTY OF THE	Kemarks	
a)	Road Junction condition			
b)	Condition of Surfacing	S/U /		
c)	Riding Quality	S/U /		
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)  Yes/1			
g)	Compaction of flank/slope & raincuts if any Yes			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/			
b)	Condition of Abutment	S/SRI/U		
c)	Condition of railings/slab/approach for Bridges			H/A
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any	others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME:

Sayay Kim

DESIGNATION: