

FIELD INSPECTION REPORT

Date of Inspection: 16-12-2020 District: BANKA
 Division: BANKA-2 Length (km): 0.565
 Name of the Road: Bhagalpur Dumka Road to Makardandik (mmk, km)
 Scheme/Programme: MAINTENANCE 13rd year
 Package No.:
 Status of the Project: Road Id No.: 20702612003
 Work is a case of: Ongoing/Completed/Under Maintenance
 New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U 1/4
c)	Condition of railings/slab/approach for Bridges	S/SR/U 1/4
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Signature
 16-12-2020

NAME: AJAY KUMAR
 DESIGNATION: AE