

FIELD INSPECTION REPORT

Date of Inspection : 14.12.2020	District: Patna
Division : Besh	Length (km): 1.622 km
Name of the Road: NH 30A Bhurpura PMGSY Road to Udhwaipore	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S1
b)	Condition of Surfacing	✓ S1
c)	Riding Quality	✓ S1
d)	Road Camber	✓ S1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes No } N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes No } N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI1
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI1
c)	Condition of railings/slab approach for Bridges	S SRI1
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓ Yes No Partial
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

" SRI "

Signature: 14/12/2020

NAME: DHANANJAY KUMAR NIRALA
AE