

# FIELD INSPECTION REPORT

Date of Inspection :	18/12/2020	District :	Munger
Division :	Khagpur - Tarapur	Length (Km) :	
Name of the Road :	LO44 - Masumgay sadpur road to chafa shiv mandir		
Scheme/Programme :	MAINTENANCE		
Package No. :	BR22R109	Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	} NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U) ✓	

NAME : Suresh Kumar  
DESIGNATION : A.E

S. Kumar  
18.12.2020  
(Signature)