FIELD INSPECTION REPORT

Date of Inspection :		18.12.2020.	District :	Munger	
Division :	Khaka	9 840 - Tazapus.	Length (Km):	Munger 1-400 KM	
Name of the Road :		L091- BARUI	TO GAR	ZHI-	
Scheme/Pr	ogramme :	MAINTENANCE			
Package No. :		BR22R120	Road Id No.:		
Status of the Project :		Ongoing/Completed/Under M	laintenance	Under maintenance	
Work is a	case of :	New Connectivity/Up gradati	on/Maintenance		
Sl. No.		Parameters to be checked		Remarks	
1	Pavement			Y	
a)	Road Junctio	n condition		VS/U	14
b)	Condition of Surfacing			S/U	
c)	Riding Quality			✓S/U	
d)	Road Camber			L-STU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	NA.
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	NA-
g)	Compaction of flank/slope & raincuts if any			Yes/No	Reineuts til
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	NA-
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	MA-
3	Road Furniture			10	
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained		A. [74] 55 - 180 C405 5C 51	Yes/No_	
4	Compliance	History			
a)	Status of AT	R's & any others		No.	

Overall Rating:

Satisfacory (S)	
Satisfacory but requires Improvement (SRI)	
Unsatisfactory (U)	U.

NAME: RAMDARSHAH RAM.

DESIGNATION: J. E.

(Signature)