

FIELD INSPECTION REPORT

Date of Inspection :		District:
Division : <u>Simri Bakhtiyapur</u>		Length (km): <u>1.345 KM</u>
Name of the Road: <u>LO 41 MDR TO 5 KHAMAUTI</u>		
Scheme/Programme:		<u>MAINTENANCE</u>
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<u>S/U</u>
b)	Condition of Surfacing	<u>S/U</u>
c)	Riding Quality	<u>S/U</u>
d)	Road Camber	<u>S/U</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<u>Yes/No</u>
f)	Contraction Joints provided or not (CC Pavement)	<u>Yes/No</u>
g)	Compaction of flank/slope & raincuts if any	<u>Yes/No</u>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<u>S/SRI/U</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>S/SRI/U</u>
c)	Condition of railings/slab/approach for Bridges	<u>S/SRI/U</u>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>Yes/No</u>
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	<u>SRI</u>
Unsatisfactory (U)	

NAME:

Atagendra

Atagendra
16/12/20
(Signature)

C/S
Atagendra
16/12/2022

E.E