

FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020		District: SUPAUL
Division : R.W.D. W.DIV-VIRPUR		Length (km): 1.170 KM
Name of the Road: Haripur Panchayat REO Sadak Hanuman Nagar Mushlim Miyan ke Ghar se Madhepura U. N. Hote Hye.		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 2100501206
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	---
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	---

NAME: Budh Singh (A.F.) JE
RWD Division Virpur.
16/12/20

16.12.20
 (Signature)
A T