


FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020		District : Purnea
Division : Purnea		Length (Km) : 1.471 KM
Name of the Road : G3 Godam to sharma Jola (Petrol pump)		
Scheme/Programme : Maintenance		MMSY
Package No. : —		Road ID No. : —
Status of the Project : Ongoing/Completed/Under Maintenance		
Work is a case of : New Connectivity/Up gradation/Maintenance		
Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No ✓
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U ✓
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U ✓
3).	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
4).	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	1
	Satisfactory but requires Improvement (SRI)	1
	Unsatisfactory (U)	

Name : Chandan Kumar Bhargava
 Designation : Assistant Engineer
 RWD, Works Division, Purnea.


 (Signature)
 17/12/2020