

FIELD INSPECTION REPORT

Date of Inspection :	LT. 12. 2020	District:	Purnaa
Division :	Baisi	Length (km):	0.745 KM
Name of the Road:	Feru Pokhariya to Ghataso Purva Chowk		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 'S'
b)	Condition of Surfacing	S/U 'U'
c)	Riding Quality	S/U "U"
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 'S'
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U 'S'
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	"U"

NAME: Asim Kumar

Asim
17/12/2020
(Signature)
A. E. Batta