

FIELD INSPECTION REPORT


| | |
|---|--|
| Date of Inspection:- 17.12.20 | District:- Kishanganj |
| Division:- Kishanganj-I | Length(km): 2.061 |
| Name of the Road:- PWD road to Kumbhar Toli | |
| Scheme/Programme: MMGSY | |
| Package No.: N/A | Road Id No.: 212D5814007 |
| Status of the Project: | Ongoing/Completed /Under Maintenance |
| Work is a case of: | <input checked="" type="checkbox"/> New Connectivity/ <input type="checkbox"/> Up gradation / <input type="checkbox"/> Maintenance |

| S1. No | Parameters to be checked | Remarks |
|--------|--|----------------|
| 1. | Pavement | |
| a) | Road Junction Condition | S/U✓ |
| b) | Condition of Surfacing | S/U✓ |
| c) | Riding Quality | S/U✓ |
| d) | Road Camber | ✓S/U. |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. - N/A | Yes/No |
| f) | Contraction Joints Provided or not (CC Pavement) N/A | Yes/No |
| g) | Compaction of flank / slope & raincuts if any | Yes/No✓ |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its Painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, slab in RCC culverts | S/SRI/U |
| c) | Condition of railings/Slab/approach for Bridges | S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No✓ |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | No ATR pending |

Overall Rating :

| | |
|---|-------|
| Satisfactory(S) | - |
| Satisfactory but requires Improvement (SRI) | - |
| Unsatisfactory(U) | - U - |

NAME: Radheshyam prajapati


 17.12.20
 J.E
 R.W.D (W) Division
 Kishanganj-1