

FIELD INSPECTION REPORT


Date of Inspection : 16.12.2020		District: KISHANGANJ.
Division : KISHANGANJ-2		Length (km): 1.75.
Name of the Road: Lo 39 To Technigahi North.		
Scheme/Programme: MAINTENANCE		MMGSY.
Package No.:		Road Id No.: 21205913003
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U / S
b)	Condition of Surfacing	S/U / U
c)	Riding Quality	S/U / S
d)	Road Camber	S/U / S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No / ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No / ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No / ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U / ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U / ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U / ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No / NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: SUNIL KUMAR RANJAN.
J.E. / Digital Bank - ②

(Signature) 
16.12.2020