

FIELD INSPECTION REPORT

Date of Inspection : 17.12.20
 Division : R.N.D. Chapter 2
 District : SARAN
 Name of the Road : Dighal Chapir
 Length (km) : 1.50 K.M.
 Scheme/Programme : MAINTENANCE
 Package No. : 140404
 Road Id No. : M.M.B.S.7 Ghera
 Status of the Project : Ongoing/Completed/Under Maintenance
 Work is a case of : New Connectivity/Up gradation/ Maintenance

Sl. No. Parameters to be checked Remarks

1. Pavement

- a) Road Junction condition S/U
- b) Condition of Surfacing S/U
- c) Riding Quality S/U
- d) Road Camber S/U
- e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No
- f) Contraction Joints provided or not (CC Pavement) Yes/No
- g) Compaction of flank/slope & raincuts if any Yes/No

2. Drainage

- a) Condition of head walls in Hume pipe culverts including its painting S/SRI/U
- b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U
- c) Condition of railings/slab/approach for Bridges S/SRI/U

3. Road Furniture

- a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No

4. Compliance History

- a) Status of ATR's & any others NO

Overall Rating :

Satisfactory (S)
 Satisfactory but requires Improvement (SRI) ✓
 Unsatisfactory (U)

(Signature)

17.12.20

14/12/2020
 A.E.
 Ban. y. s. p.

E :

GNATION: