

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020	District: Nalanda
Division : Bihar Sharif	Length (km): 1.60 km
Name of the Road: Khisaura chikpur path se dhogiyakul more se Kathaulo bari tak Sadak nirman	
Scheme/Programme: MAINTENANCE 45/5	Rajya Yojana
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Note - Road crust and shoulder partially damaged due to flood 2020
DPR submitted

17/12/20

(Signature)

NAME: Bimal Kumar Singh

DESIGNATION: J.E