

FIELD INSPECTION REPORT

Date of Inspection :	17.12.2020	District:	SARAW.
Division :	Marhaurga	Length (km):	1.50 km.
Name of the Road:	Silhauri Tehla Patra & Khari Alur Tola hote here Harit Jora Tola Patra (mmary)		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Completed</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>Maintenance</u>		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	✓S/U	
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture	Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	(partly)	
4.	Compliance History	NO.	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Surface in 2nd km damage due to overtop flood / rain water in length approx - 60m.

(Signature) He 17.12.20

NAME: Devendram
DESIGNATION: AE