

# FIELD INSPECTION REPORT

|                                                               |                       |
|---------------------------------------------------------------|-----------------------|
| Date of Inspection : 17/12/20                                 | District: Nalanda     |
| Division : Bihar Sharif                                       | Length (km): 0.986 km |
| Name of the Road: Sonai Sosauni road to Hanpur via Salmabadi  |                       |
| Scheme/Programme: MAINTENANCE                                 | mm/sy (Gen)           |
| Package No.:                                                  | Road Id No.:          |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                       |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                       |

| Sl. No. | Parameters to be checked                                                                                             | Remarks      |
|---------|----------------------------------------------------------------------------------------------------------------------|--------------|
| 1.      | <b>Pavement</b>                                                                                                      |              |
| a)      | Road Junction condition                                                                                              | S/U S        |
| b)      | Condition of Surfacing                                                                                               | S/U U        |
| c)      | Riding Quality                                                                                                       | S/U S        |
| d)      | Road Camber                                                                                                          | S/U S        |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No NA    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No 428   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No No    |
| 2.      | <b>Cross Drainage</b>                                                                                                |              |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U S RI |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U MA   |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U MA   |
| 3.      | <b>Road Furniture</b>                                                                                                |              |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No No    |
| 4.      | <b>Compliance History</b>                                                                                            |              |
| a)      | Status of ATR's & any others                                                                                         | Nil          |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          | U |

Not - CC pavement damaged due to Mal Jal Yojana.

*(Signature)*  
17/12/20

NAME: Ram Akshay Ad. Binsh Yadav

DESIGNATION: Assistant Engineer