

FIELD INSPECTION REPORT

Date Of Inspection : 14/12/20 District: Siwan
 Division: Mahrajanj Length : 1.20KM
 Name Of the Road : TO 1 से बेलाग देहा
 Scheme/Programme : GITSN
 Package No. : Road Id No. :
 Status Of the Project : Ongoing/Completed/Under Maintenance
 Work is a case of : New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/✓
b)	Condition of Surfacing	S/✓
c)	Riding Quality	S/✓
d)	Road Camber	S/✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR' s & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME :
DESIGNATION :

ANAND KUMAR
AE

Aksh
14/12/20
(Signature)

MANISH KUMAR OJHA (J.E.)
14/12/20