

## FIELD INSPECTION REPORT

Date of Inspection : \		District: Muzaffar pur	
Division : RIAD Eas-	1. Hurolla Jan	Length (km):	
Name of the Road: Pro	idhan mandrisa	dax ramper hat se kampalpura	mum
Scheme/Programme:	MAINTENANCE	Length (km): 1.0  dax ramper hat se kansalpura	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintepance		
C1 31	The state of the s		7

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	·/S/U
b)	Condition of Surfacing	∠8/U
c)	Riding Quality	√S/U
d)	Road Camber	√\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	√\$/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	√es/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	CRT
Unsatisfactory (U)	- 12+

NAME:

DESIGNATION:

Tit

(Signature)

A.E. Revi)