

FIELD INSPECTION REPORT


Date of Inspection : 17.12.2020	District: Muzaffarpur
Division : East - I	Length (km): 1.35 KM
Name of the Road: PMGSY Sadak to primary School Malhwa Mukundpur	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 31507213027
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓SRI
Unsatisfactory (U)	✗

NOTE: PORTION OF BT SURFACE DAMAGED DURING FLOOD 2002 & UPGRADATION THEREAFTER.


 17.12.2020

(Signature)

NAME: ASHUTOSH KUMAR

DESIGNATION: JE. SAHA