

		FIELD INSPECTION REPORT			
Date of I	aspection:	District Control of the Control of t			1
Division: District: MVZNFARP Length (km): 2.281					
Name of	the Road: 104	B (.m.).	2.286 1		
Scheme/	Programme:		Ryapaka	r to Ray	ble mige
Package		MAINTENANCE -MMGSP-SC-	-	Ration	pur
Road Id No.: 3 5072 2003			0	1	
Being completed Order Waintenance				1	
	- case or.	New Connectivity/Up gradation/ Mainter	nance		1
Sl. No.		Parameters to be checked		Remarks	1
1.	Pavement				-
a)	Road Junction	condition			4
b)			✓S/U		
	Condition of Surfacing			~S/U	
c)	Riding Quality		S/U	1	
d)	Road Camber				4
	Whether free	from defects such as visible crack		√S/U	
c)	aggregates in	case of CC Pavement.	cs, exposed	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	1	

3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History		
4.			
a)	Status of ATR's & any others		

Condition of head walls in Hume pipe culverts including its painting

Condition of Abutment & Wing walls, Slab in RCC culverts

Overall Rating

g)

2.

a)

b)

c)

Satisfactory (S) SRI Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

Ah5hkin

Compaction of flank/slope & raincuts if any

Condition of railings/slab/approach for Bridges

Cross Drainage

(Signature)

Yes/No

S/SRI/U

S/SRI/U

-S/SRI/U

dole

NAME: ASHVASH KUSTAR DESIGNATION: SEJSAKAN