~~. hrastan

## FIELD INSPECTION REPORT

		-		*	
Date of Inspection: 17-12-20 District: Mysafferpur					
Division: Muz_East 2			Length (km): 0.755 1461		
Name of	the Road: 13a	nghang 12.10.D to	Pokhaz tak		
Scheme/I	'rogramme:	MAINTENANCE			
Package					
			I/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			_S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Yes/No				
ŋ	Contraction Joints provided or not (CC Pavement)  Yes/N			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges S/SRI/U			S/SRI/U	
3.	Road Furni	ture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance	History			
a)	Status of AT	R's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME:

 $\sim \sim$ 

DESIGNATION: 17-12-72