

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020	District: Muzaffarpur
Division : R.W.D. Muzaffarpur West	Length (km): 2.70 km
Name of the Road: Gram Dahanachakra Haza staneer kumar ke star to Gaura Puresy Sadak	
Scheme/Programme: MAINTENANCE	North road Chambharkur
Package No.: H/A	Road Id No.: 31507412070
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	x
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	x

18/12/2020
 NAME: JE Sahab Singh
 DESIGNATION:

(Signature)