FIELD INSPECTION REPORT

	The second secon	LIELD INSPES	CHONTELLORI		
Date of	Inspection :	17-12-20	District: Muzafrarpus		
DIVISION: 100.D. MUS. W.CL			Length (km):		
	of the Road:	akshmi The Ke	E Ghas to Angana Kort B.	tch Road	
	/Programme:	MAINTENANCE	41-		
Packag	of the Project:	10 10 1	Road Id No.:		
	s a case of:		d/Under Maintenance Up gradation/ Maintenance		
St. No.	The chart of the	V	The Section of the Control of the Co	Remarks	
300	Parameters to be checked			remarks.	
1,	Pavement				
a)	Road Junction condition			SAU	
b)	Condition of Surfacing			<i>∽</i> 8/U	
c)	Riding Quality			18 /U	
d)	Road Camber			√S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage			/	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRA/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/L	
c)	Condition of railings/slab/approach for Bridges			SASKIA	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/N	
4.	Compliance I	History			
a)	Status of ATR's & any others			No.	
70					

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Ajay Choudhay.

DESIGNATION: A.E