

# FIELD INSPECTION REPORT

|                                                                  |                                            |
|------------------------------------------------------------------|--------------------------------------------|
| Date of Inspection : 18.12.2020                                  | District: Muzaffarpur                      |
| Division : R.W.D. Muzaffarpur West                               | Length (km): 1.187 km                      |
| Name of the Road: Assa pati, se Horis Gulabpuri, tatmatola HHOSY |                                            |
| Scheme/Programme:                                                | MAINTENANCE                                |
| Package No.:                                                     | N/A                                        |
| Road Id No.:                                                     | 31507413052                                |
| Status of the Project:                                           | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                               | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | <b>Pavement</b>                                                                                                      |           |
| a)      | Road Junction condition                                                                                              | S/U ✓     |
| b)      | Condition of Surfacing                                                                                               | S/U ✓     |
| c)      | Riding Quality                                                                                                       | S/U ✓     |
| d)      | Road Camber                                                                                                          | S/U ✓     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No    |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No    |
| 2.      | <b>Cross Drainage</b>                                                                                                |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U ✓ |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U ✓ |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U ✓ |
| 3.      | <b>Road Furniture</b>                                                                                                |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓  |
| 4.      | <b>Compliance History</b>                                                                                            |           |
| a)      | Status of ATR's & any others                                                                                         |           |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | X |
| Satisfactory but requires Improvement (SRI) | X |
| Unsatisfactory (U)                          | U |

②  
18/12/2020  
NAME: Salehguni

(Signature)

DESIGNATION: