

FIELD INSPECTION REPORT

Date of Inspection : 14.12.2020	District: Vaibhavi
Division : Hagipur	Length (km): 0.700
Name of the Road: Ram Singh Chowk (Hanuman Mandir)	
Scheme/Programme: MAINTENANCE	to House of Baiju Nath Rai
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 5
b)	Condition of Surfacing	S/U 5
c)	Riding Quality	S/U U
d)	Road Camber	S/U 5
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No yes
g)	Compaction of flank/slope & raincuts if any	Yes/No yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 7
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR1
Unsatisfactory (U)	

Sanjay
14.12.2020
AE

(Signature)

NAME:

DESIGNATION: