## FIELD INSPECTION REPORT

Date of I	nspection:	10/12/20	District: East chambran	
Division	-		Length (km):	
Name of	the Road: H	ouse of vishn	notan Yadar to TOZ S.H. New	- harmin
	Programme:	MAINTENAN	CE GITLNY	
Package			Road Id No.:	
			pleted/Under Maintenance	
Work is	a case of:	SECURE AND PARTY OF THE PARTY O	vity/Up gradation/ Maintenance	7770000000000000000
Sl. No.	on other	Paramete	rs to be checked	Remarks
1.	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing			48/Ú
c)	Riding Quality			√S/U
d)	Road Camber			~8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			¥es/No
2.	Cross Drain	the standard of the pro-	and the second s	and the same
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/			
	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/O			
b) .	Condition of railings/slab/approach for Bridges  S/SRL			\\$/SRI∕\
c)	Road Furnit	S. ASPANNOS STORY		· · · · · · · ·
3.	A Secretary with England and the Control of the Con	All the second of the second o	Poard/km & 200m	v. /a.
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance	History		AIN
a)	Status of ATR's & any others			
				1 ( )

Overall Rating :

	15'
Satisfactory (S)	0
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	i

(Signature)

NAME: maleghulan sharmar

DESIGNATION:

J.E.