

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020		District : East Champaran	
Division : Chokia		Length (Km): 1.317 Km.	
Name of the Road : NH-28 to Sarai Been Nari			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	Yes	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3.	Road Furniture		
a)	Whether sign board/Informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Yes	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires improvement (SRI)	S
	Unsatisfactory (U)	

NAME :

DESIGNATION :

[Signature]
17/12/2020
A.E

(Signature)