

FIELD INSPECTION REPORT

Date of Inspection : 14/12/2020		District : euzh chon-paee
Division : Chale's.		Length (km): 2.575 km
Name of the Road : NH-28 to Chale's		
Scheme/Programme : MAINTENANCE		Package No. :
Status of the Project : Ongoing/Completed/Under Maintenance		Road ID No.:
Work is a case of : New Connectivity/Up Gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Free from potholes such as visible cracks, exposed aggregates in case of CC Pavement.	yes
f)	Contraction Joints provided or not (CC Pavement)	yes
g)	Compaction of flank/slope & rainouts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Kin & 200m Stones/Pavement road markings are provided and maintained	yes
4.	Compliance history	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	5 K.T.
Unsatisfactory (U)	

NAME :
DESIGNATION :

[Signature]
14/12/2020
A.C

(Signature)