FIELD INSPECTION REPORT

Division: WOMES Div - Pakidayal			District: Cast chambaxan, motion Length (km): 0.850Km	
The State of the S	ge No.:	MAINTENANCE	Read Id No.:	
Status of the Project: Ongoing/Completed		Ongoing/Completed		
	is a case of:	New Connectivity/U	p gradation/ Maintenance	
Sl. No.		Parameters to be checked		Remarks
1.	Pavement			22461/14/0011
a)	Road Junction condition			V-S/U
b)	Condition of Surfacing			⊱S/U
c)	Riding Quality			↓S/U
d)	Road Camber			↓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			_Yes/No
f)	Contraction Joints provided or not (CC Pavement)			~Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
2)	Whether sign stones/Pavemer	boards/informatory/c nt road markings are p	autionary Board/km & 200m provided and maintained	_Yes/No
1.	Compliance H	istory		
1)	Status of ATR's	& any others		NA

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: Sarway Alex

DESIGNATION: 3 C