

FIELD INSPECTION REPORT

Date of Inspection : 17/12/20		District: Nalanda	
Division : Harnaut		Length (km): 1.630 km	
Name of the Road: Nagarmausa chero p.w.D to Jankibigha.			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	U	S/U
b)	Condition of Surfacing	U	S/U
c)	Riding Quality	U	S/U
d)	Road Camber	U	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. NO		Yes/No
f)	Contraction Joints provided or not (CC Pavement) NO		Yes/No
g)	Compaction of flank/slope & raincuts if any NO		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained NO		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	✓

(Signature) 17/12/2020

NAME: RAVI KUMAR

DESIGNATION: Jr. Engineer

Scanned with CamScanner