

FIELD INSPECTION REPORT

Date of Inspection :	18-12-2020	District:	Lakhimpur
Division :	Namketiganj	Length (km):	3.85 km
Name of the Road:	L022 +0 Rakhai		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-37R-457	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	SRI	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	YES	
f)	Contraction Joints provided or not (CC Pavement)	YES	
g)	Compaction of flank/slope & raincuts if any	—	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	—	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—	
c)	Condition of railings/slab/approach for Bridges	—	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S	
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

B. Kumar
18/12/2020
(Signature)

NAME: BIPIN KUMAR

DESIGNATION: J.E.