

FIELD INSPECTION REPORT

Date of Inspection:	16/12/2020	District:	Darbhanga
Division:	Biraul	Length(Km):	2.347 Km
Name of Road:	LC25 Simari to Khatway Tol.		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓	
b)	Condition of Surfacing <i>Part surface damaged from Flood</i>	S/U ✓	
c)	Riding Quality	S/U ✓	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ S/U	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank /slope & raincuts if any	Yes/No	
2	Cross Drainage	Yes/No ✓	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	✓ S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	✓ S/SRI/U	
3	Road Furniture		
i)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	✓ Yes/No	
3	Compliance History		
i)	Status of ATR's & any others		
Overall Rating:		<i>Not - Above road surface partly damaged from Flood - 9.11/2020.</i>	
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)			

Name: *Vijay Kumar Jha*
Designation: *2.21 Road & Bridge*

(Signature)

16.12.20
A.E

Scanned by CamScanner